

Supplemental Techniques

Calibratioin of magnification

Grain Size Determination ASTM 112 : austenitic, prior Austenite

Hardness Testing – Micro and Macro

Use of the Metallograph

Volume Fraction Determination of Phases

Color Etching

These supplemental techniques may be incorporated into either of the other courses.